

Part - I

Performa For The Safety School Building
(To be filled by the Head of School / Institute)

1. Name of School CFC PUBLIC SCHOOL
2. Location BHAI RANDHIR SINGH NAGAR LDH.
3. Plot Area 2.212 ACRES
4. Plinth Area 3830 Sq. m. (41225 Sq. ft)
5. Number of Storey MULTI STOREY
6. Year of Construction of building 1977
7. Supervision of the qualified Engineer,
The following details may be given:
 - a) Name of the Engineer ER. KULWANT SINGH RAI
 - b) Address SHOP NO. 7 SYDHWAN COMPLEX
GHUMAR MANDI, LUDHIANA
 - c) Set of Structure Drawing used in the
construction if available ATTACHED NO. 2
 - d) Name of the Architect ER. KULWANT SINGH RAI
8. Whether the building has been constructed for the purpose of :
 - a) School (Yes / No) YES
 - b) Residential purpose and converted
for use as a school (Yes / No) NO
9. Materials used for Roof:
 - a) R.C.C. slabs (Yes / No) YES
 - b) R.S. Joists and Battens (Yes / No) NO
 - c) Wooden Joists and Battens (Yes / No) NO
10. Materials used for walls:
 - a) Mud Mortar (Yes / No) NO
 - b) Cement Mortar (Yes / No) YES
 - c) Plaster (i) Lime Mortar (Yes / No) NO
 - (ii) Cement Mortar (Yes / No) YES
11. Flooring :
 - a) Conglomerate (Yes / No) NO
 - b) Terrazzo (Yes / No) YES
 - c) Brick Paving (Yes / No) NO
12. Detailed Drawing indicating dimensions
of the rooms along with size and location
of doors and windows ATTACHED

Signature and stamp of
The Head of the School / Institute

Director
C.F.C. Public School
Bhai Randhir Singh Nagar,
LUDHIANA (Pb) 141001

Part-II

(To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on 23/04/25 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

The Area as written in the application form has been verified and found correct as per site.


The fee submitted is correct as per built up area of School and Govt. notification for fees.

The fee deposited by the School has been verified on portal.

This building can be safely occupied for normal use up to 31/03/2027 (indicate year up to which it can be used). MARCH - 2027

No - 92

Dt - 28/04/25


Sub-Divisional Engineer
Provincial Sub Division No.2
PWD B&R, Ludhiana.
